

BND 400-H & 600-F

Semi-Automatic, Air-Cooled, MIG Welding Gun



PARTS LIST


MADE IN USA

CM Industries, Inc. 505 Oakwood Rd. Lake Zurich, IL 60047 ph: 847-550-0033 fx: 847-550-0444

email: sales@cmindustries.com www.cmindustries.com

October 2018 v1.1

PARTS LIST - Replacement Parts for BND 400-H & 600-F



ITEM #	PART #		DESCRIPTION		
	400-H	600-F		•	
	B4491	B4591	Nozzle, 3/4" I.D.		
1	152-30-62C	152-30-75C	Nozzle, CMI Taper-LOCK™		
	See Nozzle Selection		Optional Nozzles		
2	See Contact Tip Selection		Contact Tip, Eliptical		
	See Contact Tip Selection		Contact Tip, CMI Taper-LOCK™		
	B4435		Diffuser, Short Eliptical Tip (std. 400-H)		
3	B4635		Diffuser, Long Eliptical Tip (std. 600-F)		
	154-B505		Diffuser, CMI Taper-LOCK™		
4	B4423R		Neck Insulator		
5	B5469	B4627	Neck		
6	B4466	B4613	End Fitting		
7	B4416	B4616	Cone Nut		
8	В4	804	Handle Kit		
9	B422		Trigger Switch Assembly		
10	B418		Trigger Switch Screw		
11	B1518 B608		Spacer Kit Handle Screw		
12	B4617		Spacer Insulator		
13	B2520066		Strain Relief Kit		
14	B2520041		Strain Relief Spring		
15	B1010027R		Adapter Block		
16	214		Power Pin, Tweco® #4		
17	214-1 214-116 214-332		Power Pin, Miller® Power Pin Cap, .023"-1/16" Power Pin Cap, 5/64"-3/32"		
18	214-25		Power Pin, Lincoln® PM & LF		
19	214-7		Power Pin, Lincoln® LN		
20	B5060CM		Euro Connector Plug		
21	B4816		Euro Connector Nut		
22	BGN2021		Control Plug, Miller® / Lincoln® PM		
23	B4719		Control Plug, Lincoln® LN & LF		
24	See Liner Selection		Liner		




Scan this QR Code to take you directly to the Technical Info page of cmindustries.com

Consumable Selection

Nozzles (Optional Available)

Comparable to Bernard[™] Nozzles

CM Industries Taper-LOCK™ Nozzles




400-H & 600-F

B4491 Brass 3/4" I.D. (std. 400-H)
B4591 Copper 3/4" I.D. (std. 600-F)
B4492 Brass 9/16" I.D.

B4495 Copper 9/16" I.D. B4495 Brass 5/8" I.D.

B4591HD Copper, Heavy Duty 3/4" I.D. **B4592HD** Copper, Heavy Duty 9/16" I.D.



Heavy Duty, Copper

 152-30-50C
 1/2" Bore, 1/8" Tip Recess

 152-30-62C
 5/8" Bore, 1/8" Tip Recess

 152-31-562
 5/8" Bore, 1/4" Tip Recess

 152-32-62C
 5/8" Bore, Flush Tip

 152-33-62C
 5/8" Bore, 1/8" Tip Stickout


 152-34-62C
 5/8" Bore, 1/4" Tip Stickout

Contact Tips


Comparable to Bernard™ Eliptical Contact Tips

	Short			Long	
	B7488	0.030" (0.8mm)		B1588	0.030" (0.8mm)
	B7489	0.035" (0.9mm)		B1589	0.035" (0.9mm)
	B7490	0.040" (1.0mm)		B1590	0.040" (1.0mm)
	B7491	0.045" (1.2mm)		B1591	0.045" (1.2mm)
	B7492	5/64" (2.0mm)		B1592	5/64" (2.0mm)
	B7493	3/32" (2.4mm)		B1593	3/32" (2.4mm)
	B7494	7/64" (2.8mm)		B1594	7/64" (2.8mm)
	B7495	1/8" (3.2mm)		B1595	1/8" (3.2mm)
	B7496	0.040" (1.0mm)		B1596	0.040" (1.0mm)
	B7497	0.023" (0.6mm)		B1597	0.023" (0.6mm)
	B7498	0.052" (1.4mm)	ш	B1598	0.052" (1.4mm)

CM Industries Taper-LOCK™ Contact Tips



155-1-764 7/64" (2.8mm)



Liners

15' (4.57m) Gun Lengths

B44115 for 0.035" - 0.045" wire B44215 for 0.045" - 1/16" wire B44315 for 5/64" wire B45415 for 3/32" wire B45615 for 7/64" wire 25' (7.62m) Gun Lengths

 B44125
 for 0.035" - 0.045" wire


 B44225
 for 0.045" - 1/16" wire

 B44325
 for 5/64" wire

 B45425
 for 3/32" wire

 B45625
 for 7/64" wire

Ordering Information



SAFETY WARNINGS! READ BEFORE USE



The symbols shown below are used throughout this manual to call attention to and identify possible hazards. When you see the symbol, watch out, and follow the related instructions to avoid the hazard. The safety information given below is only a summary of the more complete safety information found in the welding power source Owner's Manual.



Read and follow all Safety Standards.

Only qualified persons should install, operate, maintain, and repair this equipment. A qualified person is defined as one who, by possession of a recognized degree, certificate, or professional standing, or who by extensive knowledge, training and experience, has successfully demonstrated ability to solve or resolve problems relating to the subject matter, the work, or the project and has received safety training to recognize and avoid the hazards involved.







ELECTRIC SHOCK can kill.

- Always wear dry insulating gloves.
- Insulate yourself from work and ground.Do not touch live electrode or electrical parts.
- Replace worn, damaged, or cracked guns or cables.
- Turn off welding power source before changing contact tip or gun parts.
- Keep all covers and handle securely in place.



FUMES AND GASES can be hazardous.

- Keep your head out of the fumes.
- Ventilate area, or use breathing device. The recommended way to determine adequate ventilation is to sample for the composition and quantity of fumes and gases to which personnel are exposed.
- Read and understand the Safety Data Sheets (SDSs) and the manufacturer's instructions for adhesives, coatings, cleaners, consumables, coolants, degreasers, fluxes, and metals.



WELDING can cause fire or explosion.

- · Do not weld near flammable material.
- Do not weld on containers that have held combustibles, or on closed containers such as tanks, drums, or pipes unless they are properly prepared according to AWS F4.1 and AWS A6.0 (see Safety Standards).
- Watch for fire: keep extinguisher nearby.
- Read and understand the Safety Data Sheets (SDSs) and the manufacturer's instructions for adhesives, coatings, cleaners, consumables, coolants, degreasers, fluxes, and metals.



MOVING PARTS can injure.

- Keep away from moving parts.
- Keep away from pinch points such as drive rolls.



ARC RAYS can burn eves and skin.

Arc rays from the welding process produce intense visible and invisible (ultraviolet and infrared) rays that can burn eyes and skin. Sparks fly off from the weld.

- Wear an approved welding helmet fitted with a proper shade of filter lenses to protect your face and eyes from arc rays and sparks when welding or watching (see ANSI Z49.1 and Z87.1 listed in Safety Standards).
- Wear approved safety glasses with side shields under your helmet.
- Use protective screens or barriers to protect others from flash, glare and sparks; warn others not to watch the arc.
- Wear body protection made from durable, flame-resistant material (leather, heavy cotton, wool). Body protection includes oil-free clothing such as leather gloves, heavy shirt, cuffless trousers, high shoes, and a cap.



BUILDUP OF GAS can injure or kill.

- Shut off compressed gas supply when not in use.
- · Always ventilate confined spaces or use approved air-supplied respirator.



NOISE can damage hearing.

- Noise from some processes or equipment can damage hearing.
- Check for noise level limits exceeding those specified by OSHA.
- Use approved ear plugs or ear muffs if noise level is high.
- · Warn others nearby about noise hazard.



WELDING WIRE can injure.

Keep hands and body away from gun tip when trigger is pressed.



READ INSTRUCTIONS.

- Read and follow all labels and the Owner's Manual carefully before installing. operating, or servicing unit. Read the safety information at the beginning of the manual and in each section.
- Use only genuine replacement parts from the manufacturer.
- Perform installation, maintenance, and service according to the Owner's Manuals, industry standards, and national, state, and local codes.



HOT PARTS can burn.

- Allow gun to cool before touching.
- Do not touch hot metal.
- Protect hot metal from contact by others.

CALIFORNIA PROPOSITION 65 WARNING

This product contains chemicals, including lead, known to the State of California to cause cancer, birth defects, or other reproductive harm. Wash hands after use (California Health & Safety Code Section 25249.5)